



# Beamline Status



Henry Nebrensky

Brunel University



## Target

Installed S-series into ISIS in Dec. 2014:

- 4.3M successful pulses; expect 5M+
- Stable running at 30 deg.C
- Allowed to take 2V loss at 64/50 Hz
- Regular beam-bump tuning sessions
- Concern about continuing losses in readout fibres
  - Loopback monitoring restarted
  - Restart target run-in activity (R78)
  - Changed gains in HW and swapped fibres - stabilised

Overnight "standby" regime implemented with shifters stopping and waking target

**Shifter training is mandatory!**



## Decay Solenoid

- DS Compressor maintenance in August, include an early annual service to carry through to end StepIV, went awry; after restart suffered mysterious drops in Helium level traced to a faulty level meter.
- DS Power Supply returned during the spring running, and the DS used in running since.
- Improved alarm limits have reduced false alarms
- Overnight “standby” regime in place
- Occasional instability seen in fridge in Dec. (no ALH most of that run)
- Gas cleaned over Christmas, but fridge tripped off by compressed air failure mid-January, turbines were reluctant to restart. **Not something to repeat!**



## PA / BS / Diffuser

- PA had the 29 mm slab not correctly reading out as being raised. Not reproducible during shutdown. I've changed a couple of limit switches and improved their alignment. Readout issues believed to have been a dodgy electrical connection.  
Then yesterday all the readout seemed to have stopped working... I hope this is a C&M issue.
- BS sprang a leak in one of the circuits causing it to droop open - fixed during annual service.
- Diffuser had damaged electronics in controller repaired. Towards the end of the last run iris 4 ceased to open fully. Not seen this problem since (without field), and been unable to repeat with field without SSU.



## Conventional Magnets - 1

Currents now set via Run Control and overnight  
“standby” regime agreed

Earth-leakage measurements are being made; show  
...something. Predominantly a dependence on water  
resistivity.

Calibrations of the dipole and DS read-back currents  
checked and corrected as needed.



## Conventional Magnets - 2

- Known issue with limited cooling water
  - Trench water system working - gets the heat from the magnets into the roof water ("process water")
  - Replacement "Manager" now steps up cooling power through both chillers on roof; and also reports problems on the display outside the MLCR
  - Have managed to dissipate an extra 195kW from the magnets without worrying the cryo-compressors - compared with barely managing 70kW last cycle (when we were down a chiller but couldn't tell).
  - Have now lost chiller 1 twice: "safe" running still depends on alert shifter response to working alarms.
  - Moving conventional magnets to loading-bay chiller should improve both resilience and margins during May run



## BLOC roster

Showstopper for March running is lack of trained BLOCs and very few volunteers. Piggyback training on early March run.

**STILL** remains a potential showstopper - nearly had to cancel several shifts already.

Economic pressure is to take shifts, not BLOC. We now allow BLOCs to take the day shift - with the rider that *if they are called out overnight they can skip next day's shift.*

With 16/7 running, the only scheduled BLOC interventions are associated with the Wednesday maintenance period...

...the rest of the time it is "on-call"

**Still need new volunteers to cover May run**



## Future work:

### Short Term:

- Reinststate R78 target activity
- Extended list in MICEmine #1892

### Longer Term:

- Chilled water - transfer heat load to chiller in loading bay?
- Loss of Target System expertise
- Maintaining BLOC expertise